

SI M 51 04 03  
Body Equipment

September 2003  
Service Engineering

SUBJECT  
**Door Window Rattles When Door is Opened**

MODEL  
Cooper, Cooper S

SITUATION  
Some owners with vehicles produced prior to 4/03 may complain of a rattle from the door when the door is opened.

CAUSE  
Excessive play between the window lifter and the regulator rail.

CORRECTION  
An additional buffer to eliminate excess play has been installed in production since 4/03

**In case of a customer complaint,** these buffers may be retrofitted to earlier production vehicles.

PARTS INFORMATION

Part Number	Description	Quantity
51 33 7 132 223	Buffer	2

WARRANTY INFORMATION

Covered under the terms of the MINI New Vehicle Limited Warranty

**Defect Code**                      **51 33 93 39 00**